


FIELD SKETCH



Sketch No: 86

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\86.tif

Image Status: Image found and displayed.


NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.

DYE TESTING FORM

Sketch (NTS)

Dye Test 86

Show North Arrow



RESULT CODES		SOURCE TYPE CODES		
1. POSITIVE	1. MAIN SEWER	5. DOWN SPOUT	9. STAIRWELL DRAI	13. STORM DRAIN
2. NEGATIVE	2. SERVICE LINE	6. DWNSPT CONN.	10. FOUNDATION DRAIN	14. CATCH BASIN
3. CANNOT TEST	3. TRANSITION JOIN	7. AREA DRAIN	11. BUILDING INTERIOR	15. STORM MH
	4. CLEAN OUT	8. DRIVEWAY DRAIN	12. MH FRAME/SEAL	16. STORM DITCH

Additional Comments: HAD CAMERA PROBLEMS

Dye was seen in MH 03WW1-028.

C.B. Filled

INSPECTION REPORT

DATE: 03/29/2005	WORK ORDER:	WEATHER: CLOUDY, DRY	OPERATOR: J.A.M.	SECTION NR: 18	SECTION NAME:
PRESENT:	VEHICLE: TV 175	CAMERA: PAN/TILT	PRESET:	CLEANED: NO	RATE: 520

STREET: GLEN AVE. TEST 86 A 3	MAP #1: 1	MH: 1521351
CITY: BALTIMORE	MAP #2:	MH: 1521353
LOCALE: MAIN RESIDENTIAL STREET	TAPE #: JAM 2	TV'D LGTH: 20.93 ft

INSPECT REASON: DYE TESTING	PIPE SIZE: 8 in
SECTION TYPE: WASTEWATER	MATERIAL: VCP JT LGTH: 3 ft
AREA: 01-WR19	LINING: NO RELINING
	RSRVD:

REMARK: DYE TEST # 86 A 3

1:75	DIST	OBSERVATION	RATE	VCR #	PH
	0.00	inspection begins at upstream manhole, 1521351	0	00:14:54	
	20.63	Infiltration Gushing at joint at 12 o'clock to 12 o'clock	4	00:21:01	14a
	20.93	camera blocked, inspection abandoned, debris!	0	00:21:23	15a

INSPECTION IMAGES

CITY: BALTIMORE	STREET: GLEN AVE. TEST 86 A 3	DATE: 03/29/2005	SECTION NR: 18	SECTION NAME:
--------------------	----------------------------------	---------------------	-------------------	---------------



IMAGE: 14a, TAPE #: JAM 2, 00:21:01
20.63FT, Infiltration Gushing at joint at 12 o'clock to 12 o'clock



IMAGE: 15a, TAPE #: JAM 2, 00:21:23
20.93FT, camera blocked, inspection abandoned, debris!